

SPECIFICATION NUMBER	:	SPEC/CHD/001S/1500
TITLE	:	SODIUM SULPHIDE FLAKES 60%MIN

SR NO	PARAMETERS		SPECIFICATION
1	Na ₂ S	:	60% w/w min
2	Water Insoluble	:	0.4% w/w max
3	Fe	:	1500 ppm max
4	Na ₂ CO ₃	:	5% w/w max
5	Appearance	:	Red Flakes

Application : This chemical is used in Leather Industry

SPECIFICATION NUMBER	:	SPEC/CHD/002S/150
TITLE	:	SODIUM SULPHIDE FLAKES 60%MIN

SR NO	PARAMETERS		SPECIFICATION
1	Na ₂ S	:	60% w/w min
2	Water Insoluble	:	0.2% w/w max
3	Fe	:	150 ppm max
4	Na ₂ CO ₃	:	2% w/w max
5	Appearance	:	Yellow Flakes

Application : This chemical is used in Leather Industry

SPECIFICATION NUMBER	:	SPEC/CHD/003S/80
TITLE	:	SODIUM SULPHIDE FLAKES 60%MIN

SR NO	PARAMETERS		SPECIFICATION
1	Na ₂ S	:	60% w/w min
2	Water Insoluble	:	0.2% w/w max
3	Fe	:	80 ppm max
4	Na ₂ CO ₃	:	2% w/w max
5	Appearance	:	Yellow Flakes

Application : This chemical is used in Leather Industry

SPECIFICATION NUMBER	:	SPEC/CHD/004S/50
TITLE	:	SODIUM SULPHIDE FLAKES 60%MIN

SR NO	PARAMETERS		SPECIFICATION
1	Na ₂ S	:	60% w/w min
2	Water Insoluble	:	0.2% w/w max
3	Fe	:	50 ppm max
4	Na ₂ CO ₃	:	2% w/w max
5	Appearance	:	Yellow Flakes

Application : This chemical is used in Leather Industry

SPECIFICATION NUMBER	:	SPEC/CHD/005S/30
TITLE	:	SODIUM SULPHIDE FLAKES 60%MIN

SR NO	PARAMETERS		SPECIFICATION
1	Na ₂ S	:	60% w/w min
2	Water Insoluble	:	0.05% w/w max
3	Fe	:	30 ppm max
4	Na ₂ CO ₃	:	2% w/w max
5	Appearance	:	Yellow Flakes

Application : This chemical is used in Leather Industry

SPECIFICATION NUMBER	:	SPEC/CHD/006S/20
TITLE	:	SODIUM SULPHIDE FLAKES 60%MIN

SR NO	PARAMETERS		SPECIFICATION
1	Na ₂ S	:	60% w/w min
2	Water Insoluble	:	0.03% w/w max
3	Fe	:	20 ppm max
4	Na ₂ CO ₃	:	2% w/w max
5	Appearance	:	Yellow Flakes

Application : This chemical is used in Leather Industry
